

APPENDIX L

SITE RECONNAISSANCE PHOTOGRAPHS

- L-1. HOLLAND CLEANERS SITE RECONNAISSANCE EXTERIOR PHOTOGRAPHS**
- L-2. HOLLAND CLEANERS SITE RECONNAISSANCE BASEMENT PHOTOGRAPHS**
- L-3. HOLLAND CLEANERS SITE RECONNAISSANCE GROUND FLOOR PHOTOGRAPHS**
- L-4. HOLLAND CLEANERS SITE RECONNAISSANCE SECOND FLOOR PHOTOGRAPHS**

APPENDIX L-1

HOLLAND CLEANERS SITE RECONNAISSANCE EXTERIOR PHOTOGRAPHS

**APPENDIX L-1. HOLLAND CLEANERS SITE RECONNAISSANCE EXTERIOR PHOTOGRAPHS
LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING**

Holland Cleaners (502 Grand Avenue)

Site Reconnaissance Exterior photographs collected 04/09/2014



Picture 1.1: East facing exterior wall of Holland Cleaners. Several vents and drains can be seen along this wall.



Picture 2.2: Vents and drains along the east facing exterior wall showing signs of staining, paint chipping, and buildup.

**APPENDIX L-1. HOLLAND CLEANERS SITE RECONNAISSANCE EXTERIOR PHOTOGRAPHS
LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING**



Picture 3.3: Vents and drains along the east facing exterior wall and roof. The building wall in the left of the photograph is north facing wall of the WYO Theater. Paint chipping that is shown in Picture 1.4 can be seen beyond the gutter drain.



Picture 4.4: A spot of chipped paint on the north facing wall of the WYO Theater adjacent to the south wall of Holland Cleaners and near the roof mounted vents.

**APPENDIX L-1. HOLLAND CLEANERS SITE RECONNAISSANCE EXTERIOR PHOTOGRAPHS
LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING**



Picture 5.5: Facing east, looking at the west facing door of the boiler room. There were two unidentified 55 gallon drums (shown in Picture 1.6), one which was not fully sealed. The spot shown in Picture 1.4 can be seen at the right of this photograph.



Picture 6.6: Two unidentified 55 gallon drums, a plastic 35 gallon container of unidentified sitting liquid, and municipal waste in front of the boiler room on the south side of the building.

**APPENDIX L-1. HOLLAND CLEANERS SITE RECONNAISSANCE EXTERIOR PHOTOGRAPHS
LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING**



Picture 7.7: Capped and broken piping in the floor at the entrance to the boiler room on the south side of the property. Installed approximately 10 years ago, per Ms. Holland.



Picture 8.8: Boiler room attached to the south side of the property

**APPENDIX L-1. HOLLAND CLEANERS SITE RECONNAISSANCE EXTERIOR PHOTOGRAPHS
LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING**



Picture 9.9: Municipal waste in front of the boiler room on the south side of the building.



Picture 10.10: Municipal waste in front of the boiler room on the south side of the building on top of a locked unknown vault.

APPENDIX L-2

HOLLAND CLEANERS SITE RECONNAISSANCE BASEMENT PHOTOGRAPHS

APPENDIX L-2. HOLLAND CLEANERS SITE RECONNAISSANCE BASEMENT PHOTOGRAPHS
LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING

Holland Cleaners (502 Grand Avenue)

Site Reconnaissance Basement photographs collected 04/09/2014



Picture 2.1: Air compressor unit with a spill that has been covered in an absorbent.



Picture 2.2: The air compressor shown in Picture 3.1. The photograph on the right shows another angle of the spill that was covered in an absorbent.

**APPENDIX L-2. HOLLAND CLEANERS SITE RECONNAISSANCE BASEMENT PHOTOGRAPHS
LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING**



Picture 2.3: A second air compressor located above the oil spill that was covered in an absorbent. In the center of this photograph there is a 15.5 gallon beer keg that has had the top cut off. On the left side of the photograph there is a sealed drum (approximately 30 gallons) underneath another drum with an open top.



Picture 2.4: The stacked drums and the converted beer keg shown in Picture 3.3.

**APPENDIX L-2. HOLLAND CLEANERS SITE RECONNAISSANCE BASEMENT PHOTOGRAPHS
LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING**



Picture 2.5: A drain near the center of the basement.



Picture 2.6: A capped pipe sticking out of the basement floor.

**APPENDIX L-2. HOLLAND CLEANERS SITE RECONNAISSANCE BASEMENT PHOTOGRAPHS
LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING**



Picture 2.7: A drain along the east wall of the basement which appeared to have a dark liquid draining



Picture 2.8: Water filter and dry vacuum units.

APPENDIX L-2. HOLLAND CLEANERS SITE RECONNAISSANCE BASEMENT PHOTOGRAPHS
LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING



Picture 2.9: A large tank containing an unknown liquid.



Picture 2.10: Several containers of stain remover and other chemicals.

**APPENDIX L-2. HOLLAND CLEANERS SITE RECONNAISSANCE BASEMENT PHOTOGRAPHS
LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING**



Picture 2.11: Chipped and peeling paint on the basement walls and trim.



Picture 2.12: Old ventilation conduit in the ceiling of the basement on the west side of the property.

**APPENDIX L-2. HOLLAND CLEANERS SITE RECONNAISSANCE BASEMENT PHOTOGRAPHS
LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING**



Picture 2.13: Old wood flooring in a room on the west side of the basement with evidence of staining.

APPENDIX L-3

HOLLAND CLEANERS SITE RECONNAISSANCE GROUND FLOOR

APPENDIX L-3. HOLLAND CLEANERS SITE RECONNAISSANCE GROUND FLOOR PHOTOGRAPHS, LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING

Holland Cleaners (502 Grand Avenue)

Site Reconnaissance Ground Floor photographs collected 04/09/2014



Picture 3.1: Front access of dry cleaning machine. Holland Cleaners representative noted there may still be PCE in the machine.



Picture 3.2: 3 gallon Cornelius Keg filled with unknown substance. Sight glass for PCE storage in the large dry cleaning machine shown in Picture 2.1.

APPENDIX L-3. HOLLAND CLEANERS SITE RECONNAISSANCE GROUND FLOOR PHOTOGRAPHS, LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING



Picture 3.3: Rear access to the large dry cleaning machine. There are two plastic barrels (approximately 15 gallons capacity) that were less than half full containing an unknown substance and one 30 gallon drum likely containing PCE per the Holland Cleaner representative.



Picture 3.4: A closer picture of the plastic barrel shown in Picture 2.3. The photograph on the right shows two drums (approximately 15 gallon capacity) likely containing waste product per the Holland Cleaner representative.

APPENDIX L-3. HOLLAND CLEANERS SITE RECONNAISSANCE GROUND FLOOR PHOTOGRAPHS, LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING



Picture 3.5: Rear access to the smaller dry cleaning machine.



Picture 3.6: Two unidentified 55 gallon drums.

APPENDIX L-3. HOLLAND CLEANERS SITE RECONNAISSANCE GROUND FLOOR PHOTOGRAPHS, LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING



Picture 3.7: Multiple five gallon containers of oxidizing and corrosive substances.



Picture 3.8: Various dry cleaning and pressing machinery located on the ground floor in front of the west facing windows.

APPENDIX L-3. HOLLAND CLEANERS SITE RECONNAISSANCE GROUND FLOOR PHOTOGRAPHS, LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING



Picture 3.9: Boxed hangers located in what was the kitchen in the original house.



Picture 3.10: Computers, printers, and filing equipment on the upper part of the split level ground floor.

APPENDIX L-3. HOLLAND CLEANERS SITE RECONNAISSANCE GROUND FLOOR PHOTOGRAPHS, LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING



Picture 3.11: Ironing and pressing equipment.



Picture 3.12: Front desk and register area. Grand Avenue and the Albany County Courthouse can be seen through the window.

APPENDIX L-4

HOLLAND CLEANERS SITE RECONNAISSANCE SECOND FLOOR

APPENDIX L-4. HOLLAND CLEANERS SITE RECONNAISSANCE SECOND FLOOR PHOTOGRAPHS, LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING

Holland Cleaners (502 Grand Avenue)

Site Reconnaissance Second Floor photos collected 04/09/2014



Picture 4.1: Unfinished attic space.



Picture 4.2: Chipped and peeling paint on walls and windows of the second floor. Potential asbestos containing materials on wall.

APPENDIX L-4. HOLLAND CLEANERS SITE RECONNAISSANCE SECOND FLOOR PHOTOGRAPHS, LARAMIE 3RD STREET PCE ORPHAN SITE, LARAMIE, WYOMING



Picture 4.3: Chipped and peeling paint on walls and windows of the second floor bathroom.



Picture 4.4: Chipped and peeling paint on walls and ceiling of the second floor bathroom.