

**BEFORE THE
DEPARTMENT OF ENVIRONMENTAL QUALITY**

STATE OF WYOMING

IN THE MATTER OF THE
NOTICE OF VIOLATION
ISSUED TO:

Uinta County Commissioners)
Bridger Valley Landfill (10.650)) DOCKET NO. 4769-10
225 Ninth St.)
Evanston, WY 82930)

NOTICE OF VIOLATION

NOTICE IS HEREBY GIVEN THAT:

On August 30, 2010, Department personnel, Mr. Gary Keene and Mr. Charles Plymale, conducted an inspection of the Uinta County, Bridger Valley Landfill (10.650), for the purpose of verifying compliance with the Wyoming Solid (SWRR) and Hazardous Waste Rules and Regulations (HWRR). During the 8/30/2010 inspection, the following violations were found:

Count 1: The facility was unable to provide adequate evidence that the generator took the required steps to stop, contain and clean up and properly manage the released used oil and other materials. The facility was unable to provide adequate evidence that the generator took the required steps to repair/replace any leaking used oil container/tanks before returning them to service. [HWRR, Chapter 12, Section 11(c)(iv)(A-D)].

Count 2: The facility has not taken adequate measures to control windblown litter on the site [SWRR, Chapter 2, Section 4(n), 5(l)].

Count 3: The facility equipment and standby equipment are not properly maintained and/or there is no backup equipment available [SWRR, Chapter 2, Section 5(c)].

Count 4: The landfill working face was not being confined to the smallest possible area [SWRR, Chapter 2, Section 5(o)].

Count 5: Wastes at the landfill were not being adequately compacted as necessary to reduce long-term settling and conserve landfill space [SWRR, Chapter 2, Section 5(p)].

Count 6: Cover at the landfill has not been placed according to the frequency and application requirements [SWRR, Chapter 2, Section 5(q)].

Count 7: The facility does not have an adequate hazardous waste screening program in place and/or has not made all necessary notifications [SWRR, Chapter 2, Section 5(f)].

Count 8: The operator has not maintained an adequate log of all litter collection activities [SWRR, Chapter 2, Section 5(y)(i)(A)].

Count 9: The operator has not maintained adequate records for wastes sold and/or salvaged from the landfill [SWRR, Chapter 2, Section 5(y)(i)(D)].



Count 10: The operator has not maintained adequate records of problems causing the operations to cease, including but not limited to fire or equipment failure. [SWRR, Chapter 2, Section 5(y)(i)(E)].

Count 11: The operator did not have a copy of the permit application prepared under Chapter 2 [SWRR, Chapter 2, Section 5(y)(ii)(A)].


Count 12: The required trench specification records are not being kept [SWRR, Chapter 2, Section 5(y)(ii)(G)].

Count 13: Trench completion dates and/or contents are not adequately recorded [SWRR, Chapter 2, Section 5(y)(ii)(H)].


ANY PERSON who violates any provision of the Environmental Quality Act, or any rules, standard, permit, license, or variance adopted thereunder, is liable to a penalty of ten thousand dollars (\$10,000) for each day of violation, which penalty may be recovered in a civil action brought by the Attorney General in the name of the People of the State of Wyoming; and

THIS NOTICE OF VIOLATION is being sent to you pursuant to Wyoming Statute 35-11-701(c) which requires that in any case of the failure to correct or remedy an alleged violation the Director of the Department of Environmental Quality shall cause a written notice to be issued and served upon the person alleged to be responsible.

Signed this 24 day of Nov, 2010.



John V. Corra
Director
Dept. of Environmental Quality



Carl Anderson, Ph.D.
Administrator
Solid and Hazardous Waste Division