

APPENDIX B: COMMENTS ON WATER QUALITY OR WATER QUALITY CHANGES FROM LANDOWNER INTERVIEWS/QUESTIONAIRES

MAP ID	SEO PERMIT NUMBER	WELL NAME	PERMITTED USE	Comments about water quality/quantity from owner
47.1	P207610.0W	MECINT CRANSTON #1	DOM	well has gone from 30 to 45 gpm; pH measured at 3.99 (date unknown), water runs light "white" opaque when first started up (2017)
25	P3581.0W	WILLIAMS #3	STK	
45.1	P207609.0W	CRANSTON HOUSE	DOM STK	No Comment Noted
48	P114433.0W	GRIFFITH #1	DOM	Water recently stained side of shed red, iron smell lessening. Doesn't do laundry when City working on wells turns laundry red, waits a week or two. Spring on NW corner of property dried up in 2015.
34	P54046W	WILLIAMS #1	STK	owner noted a bitter taste beginning with summer 2017
50	P114771.0W	THELMA #1	DOM	No Comment Noted
28 / 28.1	P143356.0W	WILLIAMS #5	STK	cattle wouldn't drink from well in 2017; owner reported pH was 6.5 Aug of 2016
49	P114770.0W	MARK #1	DOM	No Comment Noted
26	P3634.0P	WILLIAMS #2	DOM	No Comment Noted
61	P59915.0W	NORMA #1	DOM STK	water coming up into field from a formation or pipeline (pipeline)
21	P169736.0W	WILLIAMS NO 8 SHED	STK	No Comment Noted
41	P85246.0W	KETTERLING #1	DOM	No Comment Noted
24	P35815W	SHOP WELL 6	DOM STK	No Comment Noted
37	P177462.0W	OLVER #1	DOM	Water has high sodium levels
14	P79513.0W	THOLE #2	DOM STK	Owner says smell of water is getting worse, first noticed change in 2015. Also if well is left to sit on start up the water is dark colored with an odor, but clears up once pumped.
36	P206170.0W	WOLF #1	DOM	Tree has issues (Sept 2017). New well.
11	unknown	"Dewey Ranch #2"	DOM	No Comment Noted
58	P97333.0W	KATHY #1	DOM	tastes a little metallic, July 1, 2017
35	unknown	"Kanode Community Well"	DOM	No Comment Noted
57	P38110.0W	ROBIDOUX #1	DOM STK	No Comment Noted
43	P121661.0W	KANODE-1	DOM STK	No Comment Noted
56	P194216.0W	MCDONALD #1	DOM	No Comment Noted
55	P204215.0W	TAYLOR #1	DOM STK	No Comment Noted
52	P182675.0W	25 SPRING CREEK	DOM	No Comment Noted
1	unknown	unknown	STK	No Comment Noted
44	P52843.0W	MCKILLIP #1	STK	No Comment Noted
10	P173019.0W	ROWDY NO. 1	DOM	No Comment Noted
40	unknown	unknown	DOM	No Comment Noted
38	P85375.0W	Rocking-27	DOM	No Comment Noted
39	P174356.0W	AARS #3	DOM	more odor, gel on piping, tastes different (date unknown)
54	P137994.0W	SPRING CREEK - HAPONSTALL # 1	DOM	first noticed change in July 2017, smell and grey residue; also water not clear
16	P173017.0W	TIA #1	STK	Ivan reported red algae (?) in well fall 2016, clorox treatment in spring
19	P99737.0W	ANDERSON #1	DOM	No Comment Noted
8	P190417.0W	ANDERSON/JACKSON 1	DOM	No Comment Noted
18	P128570.0W	K. & R. DENNIS #1	DOM STK	have noticed low pH (5.5) over the last tests since well was installed in 2001
60	unknown	old house well	STK	No Comment Noted
63	P191804.0W	TIGGER #1	DOM STK	No Comment Noted
62	P191804W	TIGGER #2		No Comment Noted
9	P175447.0W	MEADOWLARK WELL #1	DOM	Summer 2017 water had less cleaning potential and several 8 yr old trees went from healthy to dead. Had a drilling service in June 2017 increase PSI, no changes in pressure noted, although October 2017 less pressure in house.
12.1	P91482.0W	DOC #2	DOM	No Comment Noted
15	P201020.0W	CRANSTON #1	DOM	No Comment Noted
6	P192717.0W	Mckenzie No 1	DOM	No Comment Noted
4	P176508.0W	STEVENS #1	DOM	owner reported occasional sulfur odor
3	P103869.0W	VIREN #1	DOM	owner reports occasional sulfur odor
5	P153470.0W	Hansen#1	DOM	No Comment Noted
31	P208333.0W	ENL ERLAND NO. 1	STK	No Comment Noted
46	P33805.0W	PINE RIDGE COMMUNITY CHURCH #1	DOM STK	Pump was replaced in November 2017
7	P102271.0W	RYAN #1	DOM	No changes in water quality in last 15 years
22	P193417.0W	R RANCH II	DOM	Noticed a rotten egg smell, well is only used a couple of times a week when they are there
59	P203713.0W	WHITE #1	DOM STK	No Comment Noted
32	P46170.0W	WATER WELL #1	DOM	well has always had high iron; water started leaving white crust when poured on ground
2	unknown	unknown	DOM STK	No Comment Noted
13	P5762	DEEDER No 1	STK	multifiltration system; water bright orange
17	P77560	NEIMAN ENTERPRISE #1	DOM	Started noticing a red color in Fall 2017, used to run clear
33	P101253W	Aurand #2	Dom	well had not been used in at least 7 years; never plumbed to houses due to a sulfur/oily smell
82	P204707.0W	RCWW 1	DOM	tested on 1/26/16, pH was 6.8, iron 0
83	P198336.0W	Sharon-Ken	DOM	well started drying up and went red, summer they were building the Gillette station on top of hill
45	P1333080	Earland #5	DOM STK	Well reportedly went dry in July 2017
79	Not Permitted	West Well	DOM STK	Well reportedly went dry in July 2018, drilled at same time as Earland #5
80	P208254.0W	ARNOLD ALTAFFER #3	DOM	No comment, new well
78	Not Permitted	Unknown	Unused	Strong oil odor